

From: Apakian, Mary
To: [Geiger, William](#)
Subject: Wa0145 Metal Bank Status.
Date: Friday, June 24, 2016 8:03:16 AM
Attachments: [3340011G-34.pdf](#)

More info: Chris Bond reported this am that stone placemen tis finished, the bathymetric survey was completed and from what Chris has been told it was satisfactory. They have already started what they can for the restoration (stockpiling of Reese mats and clean-up of crushed stone pads), the rest of restoration can't begin until the crane is removed the site which Environ won't allow CEI to do until they get the bathymetric survey sealed which apparently won't be until Monday/Tuesday as Chris have been told their licensed surveyor who can seal is on vacation right now.

From: Apakian, Mary
Sent: Friday, June 24, 2016 7:46 AM
To: Geiger.william@Epa.gov
Subject: FW: Report 3340011G-34 for project Metal Bank

Hi Will,

Attached is the Environ's Daily Report from yesterday. Looks like Tie Rod testing starts as planned on Monday. Not sure when site restoration will start – based on survey results.

What do you anticipate for your need of OS from CDM Smith next week?

MJ

From: Bond, Christopher D.
Sent: Friday, June 24, 2016 7:35 AM
To: Apakian, Mary <ApakianMJ@cdmsmith.com>
Subject: Fwd: Report 3340011G-34 for project Metal Bank

Get [Outlook for iOS](#)

----- Forwarded message -----

From: "Ramboll Environ [nsteenhaut@ramboll.com]" <no-reply@archisnapper.com>
Date: Thu, Jun 23, 2016 at 8:37 PM -0400
Subject: Report 3340011G-34 for project Metal Bank
To: "eemery@ramboll.com" <eemery@ramboll.com>, "jyeung@ramboll.com" <jyeung@ramboll.com>, "jvital@ramboll.com" <jvital@ramboll.com>, "hwayland@ramboll.com" <hwayland@ramboll.com>, "jcastellani@creamerenvironmental.com" <jcastellani@creamerenvironmental.com>, "gkowalski@creamerenvironmental.com" <gkowalski@creamerenvironmental.com>, "George.Horvat@exeloncorp.com" <George.Horvat@exeloncorp.com>, "Lisa.Pfeifer@pepcoholdings.com" <Lisa.Pfeifer@pepcoholdings.com>, "Richard.Blackman@pseg.com" <Richard.Blackman@pseg.com>, "PEisenhauer@pplweb.com" <PEisenhauer@pplweb.com>, "rubind@coned.com" <rubind@coned.com>, "Electrkeith.s.wesselman@constellation.com" <Electrkeith.s.wesselman@constellation.com>, "djordanger@hunton.com" <djordanger@hunton.com>, "hass.andrew@epa.gov" <hass.andrew@epa.gov>, "nsteenhaut@ramboll.com" <nsteenhaut@ramboll.com>, "TCawley@creamerenvironmental.com" <TCawley@creamerenvironmental.com>, "Bond, Christopher D." <bondcd@cdmsmith.com>, "Geiger.William@epa.gov" <Geiger.William@epa.gov>, "Travis.T.Fatzinger@usace.army.mil" <Travis.T.Fatzinger@usace.army.mil>, "David.S.Depolo@usace.army.mil"

<David.S.Depolo@usace.army.mil>, "Glazier, Steven D." <glaziersd@cdmsmith.com>, "walter@racllc.com" <walter@racllc.com>, "joe@racllc.com" <joe@racllc.com>
Cc: "nsteenhaut@ramboll.com" <nsteenhaut@ramboll.com>

Enclosed please find the Daily Report for 2016-06-23 for project Metal Bank .

Thanks,

[Turbidity_report_6_23_2016.pdf](#)

Sent with ArchiSnapper <http://archisnapper.com>